



Windows 10 Drivers for FlashScan/AutoCal V3

EFILive Support - 2020-10-29 - Comments (0) - AutoCal V3 Hardware Configuration

FlashScanV3/AutoCal V3 drivers are part of the Windows 10 installation. If the latest driver is not installed then **FlashScan/AutoCal V3** may be unable to communicate or have interrupted communications with your PC. Typically the following EFILive Error Codes are displayed:

1. \$0101 No data received during firmware update.
2. \$0020 EFILive USB driver DLL not loaded.

Users should check to see if they are running the latest windows 10 release and if it is not up-to-date inline with the version release history here

<https://docs.microsoft.com/en-us/windows/release-information/> users should update.

Find operating system info in Windows 10

1. Select the Start button > Settings > System > About . Open About settings.
2. Under Device specifications > System type, **see** if you're running a 32-bit or 64-bit **version** of **Windows**.
3. Under **Windows** specifications, **check** which **edition** and **version** of **Windows** your device is running.

Related Content

- [V3 USB FAQ](#)
- [FlashScan V3 Hardware Specification](#)